

Table of Contents

- i. Preface
- ii. Contributing Chapter Authors
- 1.0 Introduction**
 - 1.1 Washing as a Fractionation Process
 - 1.2 Early Washing Systems
 - 1.3 Modern Washing Systems
 - 1.4 Reasons for Washing
 - 1.5 Why Vacuum Drum Washers are so Important
 - 1.6 Layout of the Current Book
 - 1.7 References
- 2.0 Fundamental Factors and the Different Types of Washing**
 - 2.1 Physical Factors Impacting Washing
 - 2.1.1 Stock Type
 - 2.1.2 Stock pH
 - 2.1.3 Temperature
 - 2.1.4 Air Entrainment
 - 2.2 Operational Factors Impacting Washing
 - 2.2.1 Inlet Consistency
 - 2.2.2 Discharge Consistency
 - 2.2.3 Drum Speed
 - 2.2.4 Pulp Mat Consistency and Filtration Pressure (Pressure Washers)
 - 2.2.5 Wash Water Entering Velocity through the Pulp Mat
 - 2.2.6 Dilution Factor
 - 2.3 Fundamental Principles
 - 2.3.1 Drainage
 - 2.3.2 Diffusion
 - 2.3.3 Mechanical Compression
 - 2.3.4 Sorption
 - 2.4 Types of Washing
 - 2.4.1 Dilution
 - 2.4.2 Extraction
 - 2.4.3 Displacement
 - 2.4.4 Diffusion
 - 2.5 Acknowledgement
 - 2.6 References
- 3.0 Fundamental Design of Vacuum Washing Systems**
 - 3.1 Approach Flow Elements
 - 3.1.1 Blow Tanks
 - 3.1.1.1 Low-density dilution zone
 - 3.1.1.2 Process startups
 - 3.1.1.3 Process shutdowns
 - 3.1.1.4 Straight-sided blow tanks

- 3.1.2 Defibrilizers
- 3.1.3 Homogenization Tank
- 3.1.4 Hot-Stock Refiners
- 3.1.5 Deknotting and Screening
- 3.2 Understanding the Wash Cycle
- 3.3 Main Wash Line Components
 - 3.3.1 Filtrate Tanks
 - 3.3.1.1 Baffles
 - 3.3.1.2 Interface ratio
 - 3.3.1.3 Seal pots
 - 3.3.1.4 Vacuum breaker water seal
 - 3.3.2 Soap and Foam Handling
 - 3.3.2.1 Soap skimming from the first-stage filtrate tank
 - 3.3.2.2 Continuous foam handling
 - 3.3.2.3 Foam lines
 - 3.3.2.4 Foam breakers
 - 3.3.3 Vacuum Drum Construction and Operation
 - 3.3.3.1 Approach flow feed piping
 - 3.3.3.2 Inlet box
 - 3.3.3.3 Cylinder design
 - 3.3.3.4 Droplegs
 - 3.3.3.5 Valve timing
 - 3.3.3.6 Countercurrent shower flow
 - 3.3.3.7 Nozzles and weir showers
 - 3.3.3.8 Air doctor takeoff
 - 3.3.3.9 Intermediate submerged repulpers
 - 3.3.3.10 Washer hoods

3.4 References

4.0 Washing Efficiency Calculations

- 4.1 Specific Loading
- 4.2 Dilution Factor (*DF*)
- 4.3 Wash Ratio (*WR*)
- 4.4 Displacement Ratio (*DR*)
- 4.5 Thickening Factor (*TF*)
- 4.6 Overall Washing Efficiency
- 4.7 Equivalent Displacement Ratio (*EDR*)
- 4.8 Solids Reduction Ratio
- 4.9 The Norden Efficiency Factor
- 4.10 Modified Norden Number
- 4.11 Converting Between EDR and Modified Norden (E_{10}) Number
- 4.12 Process Implications
 - 4.12.1 Inlet Vat Consistency
 - 4.12.2 Drum Speed on Vacuum Washers
 - 4.12.3 Equipment Type Considerations

4.13 References

5.0 Modern Washing Processes

5.1 In-Digester Washing

5.2 Diffusion Washing

5.2.1 Atmospheric Diffusion Washers

5.2.2 Pressurized Diffusion Washers

5.3 Horizontal Belt Washers

5.4 Rotary Pressurized Drum Washers

5.4.1 Compaction Baffle (CB) Washer (Filter)

5.4.2 Displacement Drum (DD Washer)

5.5 Extraction Presses

5.5.1 Twin-Roll Presses

5.5.2 Screw Presses

5.6 References

6.0 Wash Water Quality

6.1 Sources of Wash Water

6.1.1 Difficulties associated with specific water sources

6.1.2 Modification of wash water to enhance performance (CO₂ and pH modification)

6.1.3 Condensates Used in Washing

6.1.4 Stripping (cleaning) of foul condensates for reuse as brownstock wash water

6.1.4.1 Types of Strippers

6.1.4.1.1 Air Strippers

6.1.4.1.2 Steam Strippers

6.1.4.2 Integrating BOD-type steam strippers into evaporator systems

6.1.5 Anaerobic Treatment of Condensates

6.2 Condensate Impact on Washing

6.3 References

7.0 Impact of Extended and Oxygen Delignification upon Brownstock Washing

7.1 Extended Delignification

7.2 Oxygen Delignification

7.2.1 Chemistry

7.2.2 Process Reaction Conditions

7.2.2.1 Alkali Charge

7.2.2.2 Temperature

7.2.2.3 Retention Time

7.2.2.4 Oxygen Charge

7.2.2.5 Consistency

7.2.3 Carryover (raw) and carryback (oxidized) solids impact on oxygen delignification

7.2.3.1 Delignification

7.2.3.2 Viscosity

7.3 Post-Oxygen Washing

7.4 References

8.0 Trace Metals in Brownstock Washing

8.1 Principles Regarding Calcium in Kraft Cooking and Washing

8.2 Causticizing and White Liquor

8.2.1 Causticizing

8.2.2 Clarification and Filtration

8.2.3 White Liquor and Wood Chips

8.3 Heat Impacts

8.4 Calcium Solubility in Digesters

8.5 Technical Analysis

8.5.1 Catechol Influence

8.5.2 Pyrogallol Influence

8.5.3 Chelation

8.5.4 Supersaturation

8.5.5 Inhibition of Precipitate Growth

8.6 Digester Scale

8.7 Scale in Brownstock Washing

8.8 Conclusions

8.9 References

9.0 Process Upsets, Troubleshooting, and Optimization

9.1 Process Upsets

9.1.1 Consistency Upsets

9.1.2 Temperature

9.1.3 Pitch Problems

9.1.4 Production Rate Changes

9.1.5 Swinging Wood Species between Softwood and Hardwood

9.1.6 Blending Pine and Hardwood Black Liquors

9.2 Mechanical Issues Resulting in Upsets and Long-Term Operating Difficulties

9.2.1 Plugging and Breaking

9.2.2 Consistency and Flow Meters

9.2.3 Valve Stiction

9.3 Understanding the Basic Washing Principles to be Optimized

9.3.1 Diffusion Equilibrium

9.3.2 Dilution Washing

9.3.3 Extraction Washing

9.3.4 Displacement Washing

9.3.5 Interactions

9.4 Preparation for Troubleshooting and Optimization

9.4.1 Mechanically Sound Operation

9.4.2 Operating Procedures

9.4.3 Statistical Process Control Charts for Performance Stability

9.4.4 Specific Loading and Washer Performance

9.4.5 Washing Efficiency

9.4.6 Sampling

9.5 Troubleshooting

9.5.1 Treating Symptoms versus Root Cause Analysis

9.5.2 Individual Stage and Component Optimization

9.5.2.1 Pulp Mat Profile

9.5.2.2 Inlet Piping

9.5.2.3 Inlet Box

9.5.2.4 Inlet Weir

9.5.2.5 Showers and Displacement Washing

9.5.2.6 Tramp Water Infiltration

9.5.2.7 Wash Water Temperature

9.5.2.8 Entrained Air

9.5.2.9 Drum Vacuum

9.5.2.10 Seal Tanks

9.5.3 Process Modeling

9.6 References

10.0 Material Balance Principles

10.1 Fundamentals

10.2 Brownstock Operations

10.2.1 Batch Digesters

10.2.2 Continuous Digesters

10.2.3 Washers

10.2.3.1 Vacuum Washers

10.2.3.2 Wash Presses

10.2.3.3 Diffusers

10.2.3.4 DD Washers

10.2.3.5 Chemi-Washers

10.2.3.6 Digester Washing

10.2.4 Oxygen Delignification

10.2.5 Screening and Refining

10.2.6 Vacuum Washer Thermal Aspects

10.3 Reconciling Balances with the Real World

10.4 Characterizing Losses

10.5 References

11.0 Pulp Washing Models

11.1 Introduction

11.2 General Assumptions

11.3 Steady-State Models

11.3.1 Black-Box Models

11.3.1.1 Split Shower/Decanter Model

11.3.1.2 Nordén's Efficiency Factor Model

11.3.1.3 Perfect Mixing Cells in Series (PMCS) Model

- 11.3.2 Fundamental Models
 - 11.3.2.1 Dispersion Models
 - 11.3.2.2 Mass Transfer Models
- 11.3.3 Statistical Models
- 11.3.4 Wash Press Models
- 11.3.5 Global Steady-State Models of Washer Systems
- 11.4 Dynamic Models
- 11.5 Model Applications
- 11.6 References
- 12.0 Pulp Consistency Control**
 - 12.1 Defining and Determining Pulp Consistency
 - 12.1.1 Determining Pulp Consistency: Sampling and Laboratory Analysis
 - 12.1.2 Choosing a Suitable Sampling Device and Deciding on its Positioning
 - 12.1.3 Choosing the Sampler
 - 12.1.4 Positioning the Sampling Valve in the Process
 - 12.1.5 Accurate Analysis of Consistency Samples
 - 12.1.6 Medium-Consistency Considerations in the Pulp Mill
 - 12.1.7 Homogeneity
 - 12.1.8 Flow
 - 12.1.9 Factors Affecting Flow
 - 12.2 Typical Control Loop
 - 12.2.1 The pulp chest and its agitation
 - 12.2.2 The Stock Pump
 - 12.2.3 Dilution Water Supply
 - 12.2.4 Dilution Water Valve
 - 12.2.5 Valve Characteristics
 - 12.2.6 Water Injection
 - 12.2.7 Consistency Transmitter
 - 12.2.8 Controller
 - 12.3 Planning the Consistency Control Loop
 - 12.3.1 Typical Dilution Stages
 - 12.3.2 Designing the Process to Achieve Correct Consistency at the Dilution Stage
 - 12.3.3 Double Dilution Stage
 - 12.4 Consistency Application Examples
 - 12.4.1 Controlling Consistency after a Continuous Digester
 - 12.4.1.1 Transmitter Selection
 - 12.4.1.2 Control Strategy
 - 12.4.2 Controlling Consistency after the Blow Tank
 - 12.4.2.1 Transmitter Selection
 - 12.4.2.2 Control Strategy
 - 12.4.3 Controlling Consistency after a Medium-Density Tower
 - 12.4.4 After the MC Storage Tower

- 12.4.5 Controlling Consistency at a Refiner
- 12.5 Reference
- 13.0 Instrumentation for Cooking, Refining, Screening, and Washing**
 - 13.1 Flow Meters
 - 13.1.1 Magnetic Flow Meter
 - 13.1.2 Vortex Flow Meter
 - 13.1.3 Differential Pressure Flow Meter
 - 13.1.4 Thermal Flow Meter
 - 13.1.5 Ultrasonic Flow Meters
 - 13.1.6 Sonar Flow Meter
 - 13.1.7 Coriolis Mass Flow and Density Meter
 - 13.1.8 Turbine Flow Meter
 - 13.1.9 Positive Displacement Flow Meter
 - 13.1.10 Flow Meter Reference Table
 - 13.2 Consistency Meters
 - 13.2.1 Blade-Type Meters
 - 13.2.2 Rotary Meters
 - 13.2.3 Optical Meters
 - 13.2.4 Microwave Meters
 - 13.3 Fiber Analyzers
 - 13.3.1 Classification (Bauer-McNett)
 - 13.3.2 Freeness (Online & Manual)
 - 13.3.3 Morphology, Dirt, and Shives
 - 13.4 Kappa Analyzers
 - 13.4.1 Manual and Auto-Titration Laboratory Testing
 - 13.4.2 Online Kappa Analyzer
 - 13.4.3 Single-Point and Multi-Point Analyzers
 - 13.5 Temperature Sensors
 - 13.5.1 Common Temperature Probes
 - 13.5.2 Proper selection and installation of temperature probes
 - 13.6 Level Sensors
 - 13.6.1 Float transmitters
 - 13.6.2 Bubbler transmitter
 - 13.6.3 Differential pressure transmitter
 - 13.6.4 Radar or microwave units
 - 13.6.5 Ultrasonic or sonic meters
 - 13.6.6 Radio frequency (RF) meters
 - 13.7 Conductivity Sensors
 - 13.7.1 Contacting or Potentiometric Sensors
 - 13.7.2 Inductive or Toroidal Sensors
 - 13.8 Dissolved Lignin Sensors
 - 13.9 pH Meters
 - 13.10 Entrained Air Meters

- 13.11 Liquor Solids Meters
- 13.12 Filtrate Extractors
- 13.13 Pressure and Vacuum Gauges
- 13.14 Sample Valves
- 13.15 References
- 14.0 Process Control of Brownstock Washers**
 - 14.1 Process Control Objectives
 - 14.1.1 Protection of Personnel, Equipment, and the Environment
 - 14.1.2 Variability Reduction
 - 14.1.3 Brownstock Washer Example
 - 14.2 Three Fundamental Components of Single-Loop Control
 - 14.2.1 Sensors and Measurements
 - 14.2.2 Controllers
 - 14.2.3 Final Control Elements (Actuators)
 - 14.3 Single-Loop Control Dynamics
 - 14.3.1 Process Disturbances
 - 14.3.2 Control System Disturbances
 - 14.3.3 Process Material Disturbances
 - 14.3.4 Short-Term versus Long-Term Disturbances
 - 14.3.5 Random versus Assignable Cause Disturbances
 - 14.3.6 Time-Domain Terms
 - 14.3.6.1 Deadtime
 - 14.3.6.2 Time Constant
 - 14.3.6.3 Gain
 - 14.3.6.4 Gain Expressions in a Single Loop
 - 14.3.6.5 Linear versus Nonlinear Process Gain
 - 14.4 The PID Loop
 - 14.4.1 The Self-Regulating Loop
 - 14.4.2 The Non-Self-Regulating (Integrating) Loop
 - 14.4.3 Identifying Self-Regulating versus Integrating Loops in the Field
 - 14.5 Controller Loop Pre-Tuning Considerations
 - 14.5.1 Process Modeling
 - 14.5.2 Open-Loop versus Closed-Loop
 - 14.5.3 Process Steps to Determine Process Gain, Deadtime, and Time Constant
 - 14.5.4 Step Test Method 1
 - 14.5.5 Step Test Method 2
 - 14.5.6 Defining Process Needs
 - 14.5.7 Common Loop Types
 - 14.5.8 Control Loop Block Diagram
 - 14.5.9 Tuning Parameter Gains
 - 14.6 Common Tuning Methods
 - 14.6.1 Ziegler-Nichols and Cohen-Coon

- 14.6.2 Lambda Tuning
- 14.6.3 PID Tuning Relationship to Time-Domain Parameters
- 14.6.4 Ideal form of the PID Loop
- 14.6.5 Damping and Filtering
 - 14.6.5.1 Damping
 - 14.6.5.2 Filtering
- 14.6.6 Loop Performance
- 14.7 Laplace Transforms and Transfer Functions
- 14.8 Control Strategy and Design Considerations
 - 14.8.1 Feedback Control (FB)
 - 14.8.2 Feedforward Control (FF)
 - 14.8.3 PID Control
 - 14.8.4 Cascade Control
 - 14.8.5 Ratio Control
 - 14.8.6 Smith Predictor
 - 14.8.7 Calculator Algorithms and Function Blocks
- 14.9 Actuators: Final Control Elements
 - 14.9.1 Variable-Speed Motors
 - 14.9.2 Servomotors
 - 14.9.3 Stepper Motors
 - 14.9.4 Dampers
 - 14.9.5 Linearizing Nonlinear Actuators
- 14.10 Control Valves
 - 14.10.1 Linear Valves
 - 14.10.2 Equal Percentage Valves (EPV)
 - 14.10.3 Quick-Opening Valves (QOV)
 - 14.10.4 Valve Stiction
 - 14.10.5 Valve Hysteresis
 - 14.10.6 Valve Backlash
- 14.11 Control Valve Sizing
 - 14.11.1 Cv
 - 14.11.2 Volumetric Flow
 - 14.11.3 Mass Flow
 - 14.11.4 Compressible Liquids
 - 14.11.5 Stock Valve Sizing
 - 14.11.6 Stock Valve Sizing Example
- 14.12 Higher-Level Advanced Controls
 - 14.12.1 Advanced Regulatory Control
 - 14.12.2 Building a Dilution Factor Algorithm
 - 14.12.3 APC
 - 14.12.4 Higher-Level Control Technology and Strategy
 - 14.12.5 Model Predictive Control (MPC)
 - 14.12.6 First-Principles Models

- 14.12.6.1 Regression Models
- 14.12.6.2 Inferential Sensing
- 14.12.7 Model Fidelity Issues
 - 14.12.7.1 Adaptive Control and Model Robustness
 - 14.12.7.2 Robust Control
- 14.12.8 Statistical Process Control (SPC)
- 14.12.9 Multivariable Predictive Control (MVPC)
- 14.12.10 MVPC versus Single-Loop PID
- 14.12.11 SISO versus MIMO Applied to MVPC
- 14.12.12 Designing the MIMO
- 14.12.13 MVPC Process Step Testing
- 14.12.14 Building and Implementing the Model
- 14.12.15 Operator Training
- 14.12.16 Optimizing Functions
- 14.12.17 Gain Scheduling
- 14.12.18 Sustainability Model
- 14.13 Industrial Process Control Systems
 - 14.13.1 DCS and PLC System Overlap
 - 14.13.2 Analog Controllers
 - 14.13.3 Minicomputers and Direct Digital Control (DDC)
 - 14.13.4 Digital Technology
 - 14.13.5 Architecture
 - 14.13.6 Field Elements
 - 14.13.6.1 Sensors and Measurements
 - 14.13.6.2 Inferential Measurements
 - 14.13.7 I/O Devices & Field Networks
 - 14.13.8 Wiring Options
 - 14.13.9 Field I/O Protocols
 - 14.13.10 Wireless
 - 14.13.11 Field Control
 - 14.13.11.1 Control on the Wire
 - 14.13.11.2 Single-Loop & Multi-Loop Controllers
 - 14.13.11.3 DCS and PLC Controllers
 - 14.13.12 SCADA versus DCS
 - 14.13.13 Considerations When Choosing a Controller Platform
 - 14.13.14 Alarm Management
 - 14.13.15 History Collection and Trending
 - 14.13.16 Custom Graphics
 - 14.13.17 Historians
 - 14.13.18 Control Documentation
 - 14.13.19 Further Reading
- 14.14 Discrete Logic
 - 14.14.1 Ladder Logic

- 14.14.2 Boolean Logic
- 14.15 Regulatory Control Details
- 14.16 Control Narratives
- 14.17 Acknowledgements
- 14.18 References
- 15.0 Foam Control**
 - 15.1 History of Brownstock Defoamers
 - 15.2 Foam Formation and Chemistry
 - 15.3 Pulp Mill Foam
 - 15.3.1 Problems Caused by Foam
 - 15.3.2 Defoamer
 - 15.3.2.1 Defoamer Composition
 - 15.3.2.2 Entry and Spreading Coefficients
 - 15.3.3 Mechanism
 - 15.3.3.1 Foam Destruction Mechanism
 - 15.3.3.2 Potential Mechanisms for Defoamer Exhaustion
 - 15.4 Brownstock Washing Defoamer
 - 15.5 Purpose of Brownstock Washer Defoamers
 - 15.5.1 Drainage
 - 15.5.1.1 Drainage Mechanism 1
 - 15.5.1.2 Drainage Mechanism 2
 - 15.5.1.3 Drainage and Displacement Enhancement with Adjuncts
 - 15.5.1.4 Excessive Defoamer Usage and Excessive Drainage
 - 15.5.2 Effects of Defoamer on Mill Operations
 - 15.5.2.1 Pulp Mill and Chemical Recovery Operations
 - 15.5.2.2 Paper Machine and Wastewater Treatment Operations
 - 15.6 Pitch and Deposit Problems Caused or Exacerbated by Defoamer
 - 15.7 Conclusions
 - 15.8 References
- 16.0 Hot Stock Refining, Cleaning, and Screening**
 - 16.1 Screening
 - 16.1.1 Symbols
 - 16.1.2 Multistage Cascade Systems
 - 16.1.3 Standardized Screening Terminology and Equations
 - 16.1.4 Screening Basics
 - 16.1.4.1 Consistency
 - 16.1.4.2 Floc Disruption and Destabilization
 - 16.1.4.3 Screen Room Layout
 - 16.1.5 Screening High-Yield Stock
 - 16.1.6 Knot Removal
 - 16.1.7 Bleachable Grade/Low Kappa Brownstock Screening
 - 16.2 Screening Equipment
 - 16.2.1 Knotters

- 16.2.1.1 Pressurized First-Stage Knotters
 - 16.2.1.2 Secondary-Stage Vibratory Knotters
 - 16.2.1.3 Secondary-Stage Pressurized Knot Drainer
 - 16.2.2 Vibratory Screens
 - 16.2.3 Gravity Centrifugal Screens
 - 16.2.4 Pressurized Screens
 - 16.2.5 Screen Plates
 - 16.2.5.1 Open Area
 - 16.2.5.2 Plate Types
- 16.3 Stock Cleaning
- 16.4 Hot Stock Refining
 - 16.4.1 Refining at Low Consistency for Shive Reduction
 - 16.4.2 Typical Hot Stock Refiner Installation
 - 16.4.3 Hot Stock Refiner Installation Including a Rejects Refiner
 - 16.4.4 Gap Control for Shive Reduction
 - 16.4.5 Hot Stock Refiner Plates
 - 16.4.6 Control Strategies for Low-Consistency Hot Stock Refining
 - 16.4.7 Measurement of Shive Content and Pulp Characteristics for Control
- 16.5 References
- 17.0 Impact of Washer Performance upon Other Parts of the Mill**
 - 17.1 Erratic Operation
 - 17.1.1 Screens
 - 17.1.2 Weak Black Liquor Solids and Evaporator Operation
 - 17.1.3 Oxygen Delignification Impacts
 - 17.2 Carryover Impacts
 - 17.2.1 Bleaching
 - 17.2.2 Papermaking
 - 17.2.3 Environmental Concerns and Waste Treatment
 - 17.3 Economics
 - 17.4 References
- 18.0 Valmet Brownstock Washing Solutions**
 - 18.1 TwinRoll Presses
 - 18.2 Valmet Vacuum filter type CC
 - 18.3 Atmospheric diffuser (AD)
 - 18.3.1 Working principle
 - 18.3.2 Washing efficiency
 - 18.3.3 Applications
 - 18.4 Pressure Diffuser (PD)
 - 18.4.1 Upflow Design
 - 18.4.2 Downflow Design
 - 18.4.2.1 Illustration of Design Details using a Downflow Pressure Diffuser
 - 18.4.2.2 Washing Principle

- 18.4.2.3 Pressure Diffuser Installation Options
- 18.5 Summary
- 19.0 GL&V[®] Brownstock Pulp Washing Equipment Design and Operation**
 - 19.1 Expressing Washing Performance
 - 19.2 Selection of Washing Equipment
 - 19.2.1 New Washing Line
 - 19.2.2 Upgrade of Existing Washing Lines
 - 19.3 Compact Press[®] Washer (CoP)
 - 19.3.1 Equipment Description
 - 19.3.2 Plant Design and Layout
 - 19.4 Compaction Baffle Filter (CB)
 - 19.4.1 Equipment Description
 - 19.4.2 Design and Operating Advantages
 - 19.4.3 Plant Layout
 - 19.5 CORU-DEK[®] Vacuum Washer (CD)
 - 19.5.1 Vacuum Washer Operation
 - 19.5.2 General Guidelines
 - 19.5.2.1 Vat Consistency and Submergence
 - 19.5.2.2 Displacement Showers
 - 19.5.2.3 Dropleg and Filtrate Tank Configuration
 - 19.5.2.4 Other Design Considerations
 - 19.5.3 Equipment Description
 - 19.6 CORU-LOK[™]
 - 19.7 References
- 20.0 ANDRITZ Washing Technology for Fiber Lines**
 - 20.1 Introduction
 - 20.2 Washing Technology
 - 20.2.1 Atmospheric Diffuser
 - 20.2.1.1 Design
 - 20.2.1.2 Operation
 - 20.2.1.3 Modifications and Upgrades
 - 20.2.2 Pressure Diffuser
 - 20.2.2.1 Design and Operation
 - 20.2.2.2 Turbo Pressure Diffuser
 - 20.2.2.3 Operating Experiences
 - 20.2.3 Drum Washers
 - 20.2.3.1 Vacuum Drum Filter
 - 20.2.3.2 Gas Free[™] Filter
 - 20.2.3.3 Drum Displacer[®] Washer
 - 20.2.3.4 Segregated Filtrate Circulation
 - 20.3 Washing systems
 - 20.4 References

- 21.0 Kadant Black Clawson LLC Solutions: Chemi-Washer™ Design and Implementation**
 - 21.1 Introduction
 - 21.2 Chemi-Washer™ Design
 - 21.2.1 Design Considerations
 - 21.2.2 Description of the Technology
 - 21.2.2.1 Headbox and Formation
 - 21.2.2.2 Dewatering and Washing
 - 21.2.2.3 Filtrate Handling
 - 21.2.2.4 Hood System
 - 21.2.2.5 Drive System and Wire Operation
 - 21.3 Implementation
 - 21.3.1 Washer Configuration
 - 21.3.2 Wash Water Selection
 - 21.3.3 Chemi-Washer™ Control
- 22.0 Environmental Aspects of Brownstock Washing – Air**
 - 22.1 Air Emissions from Brownstock Washers and Applicable Regulations
 - 22.1.1 Kraft Pulp Mills
 - 22.1.2 Sulfite Pulp Mills
 - 22.1.3 Semi-Chemical Pulp Mills
 - 22.1.4 Treatment of Brownstock Washer Hood Vent Gases
 - 22.2 Other Environmental Aspects of Brownstock Washing
 - 22.3 References
- 23.0 Environmental Aspects of Brownstock Washing – Water**
 - 23.1 Best Management Practices (BMP)
 - 23.1.1 Toxicity Impacts
 - 23.1.2 Fish Reproduction Impacts
 - 23.2 Effluent Reduction
 - 23.3 Monitoring and Testing of Bleach Plant and Mill Effluents
 - 23.4 Environmental Performance at Today’s Bleached Pulp Mills
 - 23.4.1 Environmental Impacts
 - 23.4.1.1 Bleached vs. Unbleached Mills
 - 23.4.1.2 Holistic, Sum-Parameter Studies
 - 23.4.2 Field Studies
 - 23.4.2.1 Fish Reproduction Studies
 - 23.4.2.2 Variability of Measurable Environmental Effects
 - 23.4.2.3 Confounding Parameters and Literature Studies
 - 23.5 Long-Term Field Assessments of Pulp Mill Effluent Effects
 - 23.5.1 Background
 - 23.5.2 Canadian Environmental Effects Monitoring Program
 - 23.5.3 U.S. Long-Term Receiving Water Study
 - 23.6 Conclusions
 - 23.7 References